Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5065**

Resource Identification

Property Name(s): ..... Redd Property (Vacant House) {Current}
Property Date: ..... ca 1940
Address(s): ..... 13137 Old Suffolk Road {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
Surrounding area. ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Central interior	Brick	Chimneys - Common Bond
Foundation	Foundation - Piers	Concrete	Foundation - Block
Porch	Porch - 1-story, 3-bay	Wood	Porch - Post, Square
Roof	Roof - Gable, Side	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Aluminum Sidin
Windows	Windows - Double-hung	Wood	Windows - 6/6

Site Description: ..... This is currently a vacant house that is located in a rural area.

Secondary Resource Desc: There are four outbuildings associated with this house.

WUZIT Count:

No.	Wuzit Types	Historic?
1	House	Historic
2	Shed	Historic
1	Barn	Historic
1	Equipment Shed	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5065**

Individual Resource Information

WUZIT: Shed

Est. Date of Construction:	1940 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Northwest of the house is a shed (A) that is clad in board-and-batten siding with a gabled roof covered in standing-seam metal.

WUZIT: Barn

Est. Date of Construction:	1940 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: The barn displays a gambrel roof that is covered in standing-seam metal and an exterior clad in weatherboard. A lean-to has been appended to the east elevation of the barn.

WUZIT: Shed

Est. Date of Construction:	1940 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: The shed (B) features a gabled roof and is entirely clad in standing-seam metal.

WUZIT: Equipment Shed

Est. Date of Construction:	1940 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: North of the house is a barn, shed (B), and equipment shed. The equipment shed is an open structure with a gabled roof covered in standing-seam metal.

WUZIT: House

Est. Date of Construction:	1940 ca {Site Visit}	*Accessed?*	No
Primary Resource?	Yes	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Built c. 1940, this vacant one-and-one-half-story Frame Vernacular style house features a wooden frame structural system that rests on brick piers with concrete block infill. The exterior of this house is covered in aluminum siding and the side-gabled roof is clad in standing-seam metal. There are two gabled dormers situated on the south slope of the roof and one large shed-roofed dormer on the north slope. A brick chimney is situated in the central interior portion of the roof. A gabled front entry porch with square wooden columns on brick piers is located on the south elevation. Fenestration consists of six-over-six wooden and several one-over-one aluminum double-hung sash windows. A gabled addition has been appended to the east elevation of the house.

Cemetery Information

Bridge Information

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5065**

National Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Domestic

Historic Time Period(s): ..... R- World War I to Present (1914 - Present)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The architectural integrity of this house has been diminished due to alterations that include replacement windows and an addition. The resource is recommended as not eligible for the NRHP under Criteria A, B C, or D.

Bibliographic Documentation

Reference #: 1
Bibliographic RecordType: ..... Survey
Author ..... CCR, Inc.
Citation Abbreviation: .....
Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	6	VDHR	2004/07/01	Farm Complex

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: .. .... Phase I Survey
Date: 2004/08/31
Organization or Person: ..... CCR, Inc.
VDHR Project ID # Associated with Event .. 2002-1760
CRM Event Notes or Comments: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2,
Cultural Resource Management Event: .. .... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: .....
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: .....